



PORT OF LONDON
AUTHORITY

Port of London Authority
Chart Correction Advice
Date: 8th June 2015




CCA No: 2015/13

Chart: Erith Reach

PLA Chart No. 329
HO Ref No. 113-329-118
Previous Chart Correction: n/a

The accompanying block correction shows the mooring buoy and two screws number (1) off Erith Causeway labelled "Armac Marine Management Ltd" have been removed from the river. Mooring buoy and sinker downriver from Erith Causeway labelled "G.Hillier (87)" have also been removed from the river.



For further information see the PLA hydrographic service website:

<http://www.pla.co.uk/Safety/PLA-Hydrographic-Service-Published-Surveys>