## U27-25

Joshua Rebbettes, Deputy Harbour Master

Published: 04/09/2025 Expires: 30/09/2025

Syon Reach


## Syon Reach - Hazard to Navigation Partially Submerged Tree



#### **NOTICE TO MARINERS**

# Syon Reach - Hazard to Navigation Partially Submerged Tree

Mariners are advised that a **HAZARD TO NAVIGATION** has been identified on the south channel edge of Syon Reach, in vicinity of Brentford Dock Entrance. The approximate position is indicated by the red circle on the chartlet below:



A large tree as pictured below, lies on the south channel edge and within the authorised channel. This tree is visible at low water however will be **partially submerged** or **fully submerged** by the tide. A small orange **unlit** buoy, has been attached to mark the position.

Telephone calls, VHF radio traffic, CCTV and radar traffic images may be recorded in the VTS Centre



## U27-25

Joshua Rebbettes, Deputy Harbour Master

Published: 04/09/2025 Expires: 30/09/2025

Syon Reach



### Syon Reach - Hazard to Navigation Partially Submerged Tree

### NOTICE TO MARINERS



Mariners are advised to navigate this area with extreme caution and report any difference in position to London VTS.

Additional information may be broadcasted by London VTS on VHF Channel 14.

Telephone calls, VHF radio traffic, CCTV and radar traffic images may be recorded in the VTS Centre

